
# DAB SFN - Single-frequency network SFN errors


Christian Strøm Broadcast System Architect
Telenor opperates 2 national DAB networks in Norway

- Comercial nettwork 250 Tx, 93,5% population coverege
- Puplic broacaster 1070 Tx 99,7% population coverege






















Signals from each transmitter will be added in the receiver.


This can be avoided/reduced by delaying some of the transmitters





Southeast part of Norway













#### **SFN** error

If one transmitter has timing issues

=> It will transmit signals at the wrong time




- => The output will cause self-interference in some areas.
  - Listeners will complain that there is no signal.
  - Close to the transmitter reception will be OK
  - You need to go out in the field and look at the impulse response





## Results using R&S ETL measuring equipment






Transmitter ID TII 43 13 - Sarpsborg



#### **SFN** errors

- Difficult to detect
  - Often listeners will complain
  - If you suspect one transmitter has a SFN error
    - You can turn it off for a short time to see if the problem disappears
       While the person who complains are on the telephone with you.
    - Sometime rebooting the transmitter, fixes the problem





#### Thank you for listening

Christian Strøm
Broadcast System Architect



Telenor Norge AS +47 918 44 258

E-mail: <a href="mailto:christian-hugo.strom@telenor.no">christian-hugo.strom@telenor.no</a>

